

FIG. 1




FIG. 2

Inquiry Form

Management No :


Base code		Name	
<p>This part cannot be installed properly to the main chassis</p> 			

Fig 3




Fig 4




Fig 5

	Inquiry contents	回答部署
01	Inquiry regarding a sales classification	5a
02	Inquiry regarding integration	5b
03	Inquiry regarding abnormal parts	5b
04	Inquiry regarding set defects	5b
05	Inquiry regarding exterior defects	5c
06	Inquiry regarding deformed	5c

Fig 6




Fig 7




Fig 8

